

Turbocharger Replacement 830323-5006S / 873767-5001S

Page 1**APPLICATION**

GTD1446VZM
VW 2.0L

**RELATED PART NUMBERS**

04L253014L / 04L253014M



**IMPORTANT**

Turbocharger 830323-5006S has been superseded by 873767-5001S.

Although 873767-5001S is the correct replacement, it is not a direct service replacement.

The EGR pipe flange position on the turbine housing differs, so the images below should be used to identify the correct configuration before installation.

If replacing 830323-5006S, please refer to page 2 before ordering or installation.

830323-5006S**873767-5001S****NEED TECHNICAL SUPPORT?**

Unsure which turbocharger you need or have a technical query?

Our experienced technical team is on hand to help identify the correct turbocharger and provide expert advice before you order.



Call: 0148 345 345



WhatsApp: 07760 518 557

Turbocharger Replacement 830323-5006S / 873767-5001S


Page 2

To replace turbocharger 830323-5006S you need to order the following:

Turbocharger 873767-5001S

From franchised VW dealer

- EGR pipe
- Gaskets
- Heatshield
- Necessary fasteners



Always verify the part number and the connecting pipe design before ordering or fitting. When replacing turbocharger 830323-5006S please ensure the EGR pipe flange position matches your requirements.

NEED TECHNICAL SUPPORT?

Unsure which turbocharger you need or have a technical query?

Our experienced technical team is on hand to help identify the correct turbocharger and provide expert advice before you order.

 Call: 0148 345 345

 WhatsApp: 07760 518 557